Syntroleum

November 7, 2002

RECEIVED
NOV 12 2002

Ms. Linda Bluestein
U.S. Dept. of Energy
1000 Independence Ave., S.W.
Washington, D.C. 20585

Dear Linda,

Per my recent email, I have enclosed the following information. The fuel nozzle/injector testing conducted by Ricardo was not attached to the noted email, but was discussed in the recent FTD Workshop.

- Syntroleum responses to "Data Gaps," as per a reporting received by Marc Goodman
- California Energy Commission test data
- Ricardo analysis of Syntroleum S-2 and BP Low Sulfur Diesel
- Ricardo fuel nozzle/injector test data

Please let us know how we can assist further.

Best regards,

David A. Sowards
Manager Business Development

DAS/bm

Enclosures

Syntroleum Corporation • 1350 South Boulder • Suite 1100 • Tulsa, Oklahoma 74119-3295 USA
(918) 592-7900 • FAX (918) 592-7979